




PARTS LIST
LINE SHAFT ASSEMBLY
SPENCER PORTA-RIG MODEL 7000

PARTS LIST
LINE SHAFT ASSEMBLY (Continued)
SPENCER PORTA-RIG MODEL 7000



COMPLETE ASSEMBLY

Part No.	Description	No. Req'd
LS-7M-1	Complete Line Shaft Assembly	
LS-7M-2	Shaft — Line	1
LS-7M-3	Sprocket — Drive 35T — 1 3/4 P Single	1
LS-7M-4	Oil Seal Race	2
LS-7M-5	Oil Seal Race	2
LS-7M-6	Anchor Plate — Bearing	2
55195	Oil Seal — National	4
22218	Bearing — SKF	2
LS-7M-21	End Place	2
LS-7M-24	Housing — Bearing	2
	2" Allen Head Cap Screw	12
CH-7M-3	Adapter — Mounting	2



SCHEMATIC DIAGRAM

FOR REFERENCE ONLY
 For **SPENCER-HARRIS** Parts
 Call **1-870-234-3264**
 Magnolia, Arkansas