





PARTS LIST

CROWN BLOCK ASSEMBLY

SPENCER PORTA-RIG MODEL 7000



Spencer-Harris of Arkansas, Inc.


For Reference Only

PARTS LIST

CROWN BLOCK ASSEMBLY (Continued)

SPENCER PORTA-RIG MODEL 7000

SCHEMATIC DIAGRAM



Part No.	Description	No. Req'd
CB-7MA	Complete Crown Block Assembly	
CB-7M-7	Sheave — 28"	5
CB-7M-4	Pin — Short	1
CB-7M-3	Pin — Long	1
CB-7M-5	Nut — Pin	2
CB-7M-6	Washer — Thrust	10
A5226TS	Bearing — Hyatt	5

Spencer-Harris of Arkansas, Inc.

For Reference Only